



Chase KinetiCore

Chasing down

VIRGINIA TECH.
HELMET RATING
5 ★★★★★




KinetiCore crumple zones take the force of the blow



ATMS Certified



Neck brace compatibility



Secure google position



Easy to operate magnetic buckle




No more pressure points

KINETICORE LAZER


Chase KinetiCore

Chasing down

VIRGINIA TECH.
HELMET RATING
5 ★★★★★




KinetiCore crumple zones take the force of the blow



ATMS Certified



Neck brace compatibility



Secure google position



Easy to operate magnetic buckle




No more pressure points

KINETICORE LAZER


Chase KinetiCore

Chasing down

VIRGINIA TECH.
HELMET RATING
5 ★★★★★




KinetiCore crumple zones take the force of the blow



ATMS Certified



Neck brace compatibility



Secure google position



Easy to operate magnetic buckle




No more pressure points

KINETICORE LAZER


Chase KinetiCore

Chasing down

VIRGINIA TECH.
HELMET RATING
5 ★★★★★




KinetiCore crumple zones take the force of the blow



ATMS Certified



Neck brace compatibility



Secure google position



Easy to operate magnetic buckle




No more pressure points

KINETICORE LAZER

Chase KinetiCore

Chasing down

VIRGINIA TECH.
HELMET RATING
5 ★★★★★



KinetiCore crumple zones take the force of the blow



ATMS Certified



Neck brace compatibility



Secure google position



Easy to operate magnetic buckle




No more pressure points

KINETICORE LAZER

Chase KinetiCore

Chasing down

VIRGINIA TECH.
HELMET RATING
5 ★★★★★




ATMS Certified



Neck brace compatibility



Secure google position



Easy to operate magnetic buckle




No more pressure points

KINETICORE LAZER

Chase KinetiCore

Chasing down

VIRGINIA TECH.
HELMET RATING
5 ★★★★★




ATMS Certified



Neck brace compatibility



Secure google position



Easy to operate magnetic buckle



No more pressure points

KINETICORE LAZER